

Case Study



How we Removed and Replaced a Basement wall.

Overview

Frontier Basement Solutions was contacted by the owner of a house that said his basement wall had fallen in.





The Process

Our Approach

1. When Talking with the customer we were able to come up with a plan to temporarily support the floor until we could get out to the sight and fix the problem.
2. We decided with the age of the home and the condition of the wall that the best thing to do was to support the house with jacks and remove the foundation and wall. Form and pour a new foundation and then form and pour a new foundation wall to support the house.

Our Solution





The Results

The total process took approximately 2 weeks, and 250 man hours but we were able to provide a new foundation to an old house.

Reach Out

<i>Point of Contact</i>	<i>Phone</i>	<i>Email</i>
Nate Rice	308-765-8945	nrice@frontierbasementsolutions.com