

Case Study



Drain Tile.

Overview

Frontier Basement Solutions was contacted by a homeowner that had been getting water in her basement every time it rains. We went in and did an evaluation and decide a drain tile system would be the best solution to her problem.





The Process

Our Approach

1. When talking with the homeowner she explained that every time it rained she got water in one of her rooms downstairs.
2. We decided since the room was unfinished and used for storage it would be a better option to put in an interior drain tile system instead of digging up her yard and waterproofing the exterior of the foundation wall.

Our Solution







The Results

The total process took approximately 3 days and the basement is dry. The homeowner doesn't have to worry about calling a cleaning and restoration company every time it rains. The Drain Tile Warranty will transfer with the property when the owner goes to sell the house as well.

Reach Out

Point of Contact

Nate Rice

Phone

308-765-8945

Email

nrice@frontierbasementsolutions.com